VL

FAST AND CONVENIENT INSTALLATION SYSTEM
Desk system Screen system

By XINDA

COMPONENTS

[Leg]



[Side bar]



[Connection bar]
&
[Plastic snake]



[Mid-leg]



[Table top screws M6*16]



[Table frame screws M8*12]



[Return cabinet]



[A wire box]



[B wire box]



[Countersunk cross topping screw M4*16]

[Connector]



[Countersunk cross topping screw M4*16]

[Supprtor box]



[Countersunk cross topping screw M4*16]

[H750 desk screen]



[Flat head screw M5*12]

[H350 desk screen]



[Modesty]



[Flat head screw M5*12]

[Glass desk screen
and glass chip]



[Countersunk cross topping screw M4*16]

FREESTANDING

Horizontal for frame

Round head cross screw M8*12







Vertical for top

Round head cross screw M6*16







FAST AND CONVENIENT INSTALLATION SYSTEM
Desk system Screen system

By XINDA

Manager with side table



Horizontal for frame



Countersunk cross topping screw M4*16



Round head cross screw M8*12





[Modesty]



FAST AND CONVENIENT INSTALLATION SYSTEM
Desk system Screen system

By XINDA

Manager with side cabinet

Horizontal for frame

Round head cross screw M8*12









M4*16





Vertical for top

Round head cross screw M6*16











[Modesty]



FAST AND CONVENIENT INSTALLATION SYSTEM
Desk system Screen system

By XINDA

Single side bench

Horizontal for frame

Round head cross screw M8*12





CAUTION



Vertical for top

Round head cross screw M6*16





CAUTION



M4*16

[H750 desk screen]

FAST AND CONVENIENT INSTALLATION SYSTEM
Desk system Screen system

By XINDA

Single side bench

Countersunk cross topping screw M4*16







VL

FAST AND CONVENIENT INSTALLATION SYSTEM
Desk system Screen system

By XINDA

Double side bench

Horizontal for frame

Round head cross screw M8*12





Vertical for top

Round head cross screw M6*16







FAST AND CONVENIENT INSTALLATION SYSTEM
Desk system Screen system

By XINDA

Double side bench

Countersunk cross topping screw M4*16







STEP: ①



STEP: ②



A



STEP: ③

FAST AND CONVENIENT INSTALLATION SYSTEM
Desk system Screen system

By XINDA

Double side bench

Countersunk cross topping screw M4*16





STEP: ①





STEP: ②

FAST AND CONVENIENT INSTALLATION SYSTEM
Desk system Screen system

By XINDA

Double side bench

Round head cross screw M6*16











VL

FAST AND CONVENIENT INSTALLATION SYSTEM
Desk system Screen system

By XINDA

Double side bench

Countersunk cross topping screw M4*16







SM(W+50)



MM(W+50)

Horizontal for frame

Round head cross screw M8*12







Vertical for top

Round head cross screw M6*16







FAST AND CONVENIENT INSTALLATION SYSTEM
Desk system Screen system

By XINDA

L shape workstation

Horizontal for frame

Round head cross screw M8*12





Round head cross screw M6*16





CAUTION



L shape workstation

Vertical for top

Round head cross screw M6*16





VL

FAST AND CONVENIENT INSTALLATION SYSTEM
Desk system Screen system

By XINDA

L shape workstation

Countersunk cross topping screw M4*16





A



STEP: ①



STEP: ②



A



STEP: ③

FAST AND CONVENIENT INSTALLATION SYSTEM
Desk system Screen system

By XINDA

L shape workstation

Countersunk cross topping screw M4*16











FAST AND CONVENIENT INSTALLATION SYSTEM
Desk system Screen system

By XINDA

Double side bench

Countersunk cross topping screw M4*16







SS(W+50)

Horizontal for frame

Round head cross screw M8*12







Vertical for top

Round head cross screw M6*16